

Form 874-9—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

R-19

Chippewa

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *143N* R. *29W* *5P* Mer.

Corner common to Sections *23*, *26*, and

Corner consists of a *Gravel Point* (not) in place
 State condition *Good*

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

213.8 Links

<i>S</i>	<i>1/4</i>	<i>S</i>	
<i>23</i>		<i>26</i>	

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? _____

4/2/33 (Date) *Robert Penick* (Signature) *Estimator* (Title)

R-19

Copy of sketch

Corner again.

Give any further facts which will aid in finding this

~~sketch distant.~~

from which this Corner bears

at corner


side of

the

tree *5* inches diameter, on the

Edwards

Metal Location Poster is on a



(Make sketch of topography near Corner)