

U. S. Department of Agriculture
FOREST SERVICE

Posted
61

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 N 4' R. 31 W + 30 W. 5th Mer.


Quarter Corner common to Sections
....., 12, and 7

Corner consists of a Br. cap. iron pipe (not) in place
State condition good.

Dimensions above ground 1 x 1 1/2 inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N Top S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T 148 N
R 30 W
1/4 S T

K
SIR

Metal
Poster

[Empty box]

B. T.

BT

only

[Empty box]

Species Aspen Aspen Aspen

Diameter 9" 10" 7"

Bearing S 84° 15' E S 55° 30' W S 84° 45' W

Distance 37 1/2 80 21

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

Dorman J. Sutton
(Signature)

11-9-34
(Date)

Compassman
(Title)

Corner again.

Give any further facts which will aid in finding this


..... chains distant.

from which this Corner bears *NE 1/4 1/2 E*

side of *tree*

tree *1* inches diameter, on the *NE*

Metal Location Poster is on an *Aspen*



(Make sketch of topography near Corner)

T1H3N R. 91*30W 5TH 6-1 Mer.