

C-1

U. S. Department of Agriculture

FOREST SERVICE

Posted

Chippewa NATIONAL FOREST

C1

CORNERS OF THE PUBLIC SURVEY

T. 143N R. 30W 5th Mer. Quarter

Corner common to Sections 1, and 6

Corner consists of a Br cap iron pipe (not) in place



State condition good

Dimensions above ground 1x3 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Turn. Turn.

Diameter 4" 3"

Bearing S66°E N79°W

Distance 36 48

Do you believe this to be a genuine Land Office Corner? yes

If not, why?

Dorman J. Sutton

(Signature)

12-10-34 (Date)

Compassman (Title)

Dotted lines for writing.

Corner again.

Give any further facts which will aid in finding this

chains distant.


96

from which this Corner bears *N 65° W*

side of *tree*

tree # " inches diameter, on the *NW*

Metal Location Poster is on a *Tam.*



(Make sketch of topography near Corner)

T. 143N. R. 30W. 574 Mer. C-1