

U. S. Department of Agriculture

FOREST SERVICE

Posted

Chippewa NATIONAL FOREST

C2

CORNERS OF THE PUBLIC SURVEY

T. *143N* R. *30W* *5th* Mer.



Sixteenth Corner common to Sections *6*, _____, _____, and _____

Corner consists of a *Br. cap. iron pipe* in place
State condition *good*

Dimensions above ground *1x4* inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species *Aspen Aspen*

Diameter *7" 13*

Bearing *S78°30'E N35°45'W*

Distance *35 58*

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? _____

Dorman J. Sutton

(Signature)

Compassman

(Title)

12-6-34
(Date)

Corner again.


Give any further facts which will aid in finding this

chains distant.

From which this Corner bears ³⁵ $N 78^{\circ} 30' W$

side of tree

Metal Location Poster is on a ^{Aspen} tree 7 inches diameter, on the NW



(Make sketch of topography near Corner)

T. 143N R. 30W 5th Mer. C-2