

U. S. Department of Agriculture

FOREST SERVICE

Posted J3

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 143N R. 30W 5th Mer. Quarter Corner common to Sections

7, and 18

Corner consists of a Br cap iron pipe (set) in place



State condition good

Dimensions above ground 1x6 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species R. Oak W. Oak

Diameter 16 11

Bearing N67°45'W S28°45'E

Distance 42 68

Do you believe this to be a genuine Land Office Corner? Yes.

If not, why?

Dorman J. Sutton (signature)

Compassman (Title)

12-11-34 (Date)

Corner again.

Give any further facts which will aid in finding this

chains distant.


*110 1/2*

from which this Corner bears *S 67° 45' E*

side of *tree*

tree *1/6* inches diameter, on the *S E*

Metal Location Poster is on a *Red Oak*



(Make sketch of topography near Corner)

*T. 143 N R. 30 W 5th Mer. J-3*