

U. S. Department of Agriculture

FOREST SERVICE

E-9

Poster
E9

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *143* N. R. *30* W. *5th* Mer.

Section *Section* Corner common to Sections *4, 5, 8, and 9*


Corner consists of a *brass capped pipe* in place
State condition *Good*

Dimensions above ground *12"* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species *Tamarack Slump* *Tamarack Slump*

Diameter *5"* *4"*

Bearing *546°W* *561°E*

Distance *7 lks.* *35 1/2 lks.*

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? _____

Dec 12, 1934
(Date)

Carl Steadland
(Signature)
Const. Foreman
(Title)

