

U. S. DEPARTMENT OF AGRICULTURE

FOREST SERVICE

posted

Chippewa NATIONAL FOREST 622

CORNERS OF THE PUBLIC SURVEY

T. 143N R. 30W 5th Mer.

116 Corner common to Sections
12, _____, and _____

Corner consists of a IRON POST (not) in place
State condition _____

Dimensions above ground 12" inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>1/16</u> <u>312</u>			
---------------------------	--	--	--

<u>BT</u>			
-----------	--	--	--

Species ELM _____

Diameter 13 _____

Bearing N 81 W _____

Distance 40 FT. _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

D. R. Boerner


Signature.

Estimator

Title.

12/3/1930
Date.

Metal Location Poster is on a _____ inches diameter, on the _____ side of _____ from which this Corner bears _____ chains distant. Give any further facts which will aid in finding this Corner again.



9-3021 (Make sketch of topography near Corner.)

T. 143N R. 30W 62
 Mer. 6-22