

U. S. Department of Agriculture

MINNESOTA

FOREST SERVICE MAR 10 1942

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 143 R. 30 S. 5 Mer. Corner common to Sections 1, and



Corner consists of a Brass cap (not) in place State condition Good

Dimensions above ground 10 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



S1 1/16 S-1

Species Maple

Diameter 10"

Bearing 05 30

Distance .05 ch

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? 1924 Re-survey

E. FARRELL CREECH

(Signature)

2/13/42

J (Date)

S-5

(Title)

CHICKENS
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

James Blaine, U.S. Senator

Corner again.

Give any further facts which will aid in finding the


chains distant.

from which this Corner bears S 0

side of the corner

tree 8 inches diameter, on the North

Metal Location Poster is on a Bass wood



Please sketch of topography near corner