

U. S. Department of Agriculture

FOREST SERVICE

Posted

Chippewa NATIONAL FOREST *718*

CORNERS OF THE PUBLIC SURVEY

T. *143 N.* R. *31 W.* *513* Mer.

Sixteenth Corner common to Sections

15, and *26*

Corner consists of a *Brass (spiral pipe)* (not) in place



State condition *Good*

Dimensions above ground *10* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species *P. Oak* *P. Oak*

Diameter *6"* *8"*

Bearing *N. 89° E.* *S. 42° W.*

Links Distance *101* *39*

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? _____

J. A. Gjelhaug

(Signature)

Tech. Eng.

(Title)

12/6/34

(Date)

Corner again.

Give any further facts which will aid in finding this


0.06% chains distant. 1/2 MRS.

from which this Corner bears South

side of Fence Post

two 6 inches diameter, on the N.E.

Metal Location Poster is on a Fence Post



(Make sketch of topography near Corner)

T-18 Mer.

T. 193N. R. 31W. 57A