

U. S. Department of Agriculture

FOREST SERVICE

*Posted*

*5-18*

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 143 N. R. 31 W. 5<sup>13</sup> Mer.

Sixteenth Corner common to Sections  
 \_\_\_\_\_, \_\_\_\_\_, and 26



Corner consists of a Brass Capped Pipe (not) in place  
 State condition Good

Dimensions above ground 10 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Red Oak R. Oak

Diameter 12" 14"

Bearing S 39° E N 25° E

46 1.15 1/2

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

J. A. Gjelhaug

(Signature)

Tech. Eng.


(Title)

12/6/34

(Date)

Corner again.

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant. Give any further facts which will aid in finding this



(Make sketch of topography near Corner)

T. 143N. R. 31W. 57E Mer. 5-18