

U. S. Department of Agriculture
FOREST SERVICE

Posted

Chippewa NATIONAL FOREST

R18

CORNERS OF THE PUBLIC SURVEY

T. 143N. R. 31W. 5th Mer.

Sixteenth Corner common to Sections
23, and 26



Corner consists of a Brass Capid Pipe (~~not~~) in place
State condition Good

Dimensions above ground 6 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Birch Aspen

Diameter 6" 6"

Bearing N. 68° E. S. 19 1/2° E.

40. Distance 25 1/2 69

Do you believe this to be a genuine Land Office Corner? Yes.

If not, why? _____

J. A. Gjelhaug

(Signature)

Tech. Eng.


(Title)

12/3/34

(Date)

Handwritten notes on ruled lines, including the word "Corner" and "again".

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant. Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. 193N. R. 31W. 57N. Mer. R-18