

U. S. Department of Agriculture

FOREST SERVICE

Rooted

J 19

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 143 N R. 31 W S. 5th Mer.

Corner common to Sections 14, 11, and 14

Corner consists of a Brass Capped Pipe (not) in place
State condition Good

Dimensions above ground 6 inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>14</u> <u>S 11</u>			
<u>BT.</u>			

Species N. Pine

Diameter 20"

Bearing N. 19° E.

11/13 Distance 51

Do you believe this to be a genuine Land Office Corner? Yes.

If not, why? _____

J. A. Gjelthaug
(Signature)

11/14/39
(Date)

Tech. Eng.
(Title)

Corner again.

Give any further facts which will aid in finding this


0.51 chains distant.

from which this Corner bears S 19° W.

side of *Trx*

tree 20 inches diameter, on the South

Metal Location Poster is on a N. Pine



(Make sketch of topography near Corner)

Mer. 5-19

T. 143 N. R. 31 W. 573