

U. S. Department of Agriculture

FOREST SERVICE

Posted

Chippewa NATIONAL FOREST *H20*

CORNERS OF THE PUBLIC SURVEY

T. *143 N.* R. *31 W.* *5th* Mer.

Sixteenth Corner common to Sections
 _____ and *11*

Corner consists of a *Brass capped pipe* (~~rod~~) in place

State condition *Good*

Dimensions above ground *5* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<i>SE</i> <i>1/16</i> <i>3 11</i>			
<i>B.T.</i>			

Species *J. Pine*

Diameter *12"*

Bearing *S. 51° 30' E*

115 Distance *10 7/2*

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? _____

J. A. Gjelhaug

(Signature)


Tech. Eng.

(Title)

11/26/34

(Date)

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant. Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

H-20 Mer.

T. 193N. R. 31W. 5.7N.