

Form 874-9—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

Posted

Chippewa NATIONAL FOREST 821

CORNERS OF THE PUBLIC SURVEY

T. 143N. R. 31W. 514 Mer.
Quarter Corner common to Sections

....., 23, and 29



Corner consists of a Brass Caped pipe (not) in place
 State condition Good

Dimensions above ground 6 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Aspen Aspen

Diameter 10" 9"

Bearing S49°30'E S68°W

MS. Distance 35 3/4 9

Do you believe this to be a genuine Land Office Corner? yes

If not, why?

J. A. Gjelhaug
 (Signature)

Teck. Eng.
 (Title)

11/30/34
 (Date)

Corner again.

Give any further facts which will aid in finding this


009 chains distant.

from which this Corner bears N. 68° E.

side of Tree

tree 9 inches diameter, on the N. E.

Metal Location Poster is on an ASPEN



(Make sketch of topography near Corner)

T. 143N. R. 31W. S. 17N. Mer.

P-21