

U. S. Department of Agriculture
FOREST SERVICE

Posted
L 24

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *143 N.* R. *31 W.* *5th* Mer.



4/16 Corner common to Sections
13, _____, and _____

Corner consists of a *brass capped pipe* (not) in place
State condition *Good*

Dimensions above ground *6"* inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species *W. Oak* *N. Pine*

Diameter *14"* *24"*

Bearing *S 44 1/2° E* *S 21 3/4° W*

Distance *39 lks.* *70 1/2 lks.*

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? _____

Carl Steasland
(Signature)
Const. Foreman
(Title)

Dec. 10 - 1934
(Date)

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

Mer. 1-24

R.

T.