

U. S. Department of Agriculture

FOREST SERVICE

posted

Chippewa NATIONAL FOREST

~~23~~
G-25

CORNERS OF THE PUBLIC SURVEY

T. *143* R. *31430* *5* Mer.

1/4 Corner common to Sections

.....,, *7*, and *12*
Corner consists of a *1800' post glass* (not) in place

State condition

Dimensions above ground *12* inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

<i>sec</i>		<i>sec</i>	
<i>12</i>		<i>7</i>	
N	W	S	E

NW	SW	SE	NE

Mound of is located

..... Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<i>sec 7</i> <i>143 30</i>	<i>sec 12</i> <i>143 31</i>		
<i>BT.</i>	<i>BT.</i>		

Species *Aspen*

Diameter *10"* *9"*

Bearing *S 28 E* *S 81 E*

Distance *54'* *24'*

Do you believe this to be a genuine Land Office Corner? *Yes.*

If not, why?

.....

.....

[Signature]

4/10/31


(Date)

[Signature]

(Title)

Metal Location Poster is on a _____ inches diameter, on the _____ side of _____ from which this Corner bears _____ chains distant.

Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. 143 R. 31 Mer. 6-25