

U. S. Department of Agriculture
FOREST SERVICE

Posted

5-1718

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *143N.* R. *31W.* *5th* Mer.

Meandar Corner common to Sections

.....,,, ~~and~~ *26*

Corner consists of a *Brass Capid pipe* (~~rod~~) in place

State condition *Good*

Dimensions above ground *8* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species *P. Oak*

Diameter *10"*

Bearing *N. 50 1/2 E.*

40 Distance *5 3/2*

Do you believe this to be a genuine Land Office Corner? *yes*

If not, why?

.....

.....

J. A. Gjeltrang

(Signature)

Tech. Eng.

(Title)

12/6/39
(Date)

Corner again.

Give any further facts which will aid in finding this


0.16 chains distant.

from which this Corner bears East

side of Tree

tree 8 inches diameter, on the west

Metal Location Poster is on a Root



(Make sketch of topography near Corner)

5-17-18

T. L. A. N. R. 31 W. 579 Mer.