

U. S. Department of Agriculture

FOREST SERVICE

Chippewa

NATIONAL FOREST

Q 13

CORNERS OF THE PUBLIC SURVEY

T. 144 N R. 25 W 5th Mer.

1/16 Corner common to Sections 21, and 22

Corner consists of a metal tag (not) in place



State condition good

Dimensions above ground inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

STONE CORNERS

METAL CORNERS



N W S E

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Four sets of empty boxes for sketching trees and recording bearings and distances.

Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? No

If not, why? No evidence

S. M. Morrison

(Signature)

Forestry aid


(Title)

12-16-60

(Date)

T. 144N R. 85W Mer. 57E

(Make sketch of topography near Corner and show section line markers thus "X")



Metal Location Poster is on a Bohem tree 5 inches diameter, on the East side of the from which this Corner bears 0 (Bearing) ' (Distance) Section line marker between Secs. and is on a 2 on the East (Tree, post, etc.) (Name of road, trail, etc.) located chains 1, W, N, E, S, from Sec. Cor.; $\frac{1}{4}$ Cor.; Witness Cor. (Cross out nonapplicable) Give any further facts needed to find Corner again. Blue line poster North, 100 ft 2 ft east of corner

