

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144N R. 26W 5th Mer.

1/4 Corner common to Sections

13, and 16
Corner consists of a iron capped pipe (not) in place

State condition good

Dimensions above ground 2" by 10" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S.18			
B.T.			

Species N.P.

Diameter 10"

Bearing N. 28 degrees E

Distance 34 links

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Clifford Smith
CLIFFORD SMITH

(Signature)

1/21/41


(Date)

Chief of Party

(Title)

Well placed Range line

Corner again.
Give any further facts which will aid in finding this
chains distant
from which this Corner bears
side of
tree inches diameter, on the
Metal Location Poster is on # bearing tree



(Make sketch of topography near Corner)

U. S. Department of Agriculture
FOREST SERVICE

11-18-36
123

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 R. 26-27 5th Mer.

1/4 Corner common to Sections
13, and 18

Corner consists of a Stake (not) in place
State condition

Dimensions above ground 30 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? ?

If not, why? Do NOT KNOW

No B. T's. FOUND

C. B. Stott

(Signature)

Jan. 1928

(Date)

J. F.

(Title)

to the location of the

PERSON AND

of the

and

of the

IN open bog

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 144 R. 26-27 Mer. 5-74

Form 574-B—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 N R. 26 W 5th P. Mer.



1/4 Corner common to Sections
 _____, 13, and 18

Corner consists of a iron capped pipe (not) in place
 State condition good

Dimensions above ground 2" by 10" inches
 Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species N. Pine
 Diameter 10"
 Bearing N. 28° E
 Distance 3 1/2 links

Do you believe this to be a genuine Land Office Corner? Yes
 If not, why? _____

(Signature) _____
1/21/41
 (Date) _____
 (Title) _____

Section 16, Township 36 N., Range 12 E.,

County of _____, State of _____

Section 16, Township 36 N., Range 12 E.

CORNER OF THE PUBLIC SURVEY

Well beyond Range line

Give any further facts which will aid in finding this


chains distant

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on *heavy tree*



(Make sketch of topography near Corner)

T. Lee R. 26 W. M. P. Mer.