

already posted

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST **E-1**

CORNERS OF THE PUBLIC SURVEY

T. 144N R. 26W 5th P Mer.



Sec Corner common to Sections
1, 6, 7, and 12

Corner consists of a stake (not) in place
State condition _____

Dimensions above ground 4" x 1 1/2" inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing No B.T's

Distance _____

Do you believe this to be a genuine Land Office Corner? 2

If not, why? No B.T's and no scribbles

Evidently Reestablished by

Sec. 8 subdivision surveyor

Dana F. Kirkman
(Signature)

3/12/28
(Date)

Forest Ranger
(Title)

U. S. Department of Agriculture
FOREST SERVICE

11-19-36
E-123

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 R. 26 #27 Mer.

sec

Corner common to Sections
I 6 7 and I2

Corner consists of a CEDAR POST (not) in place

State condition GOOD

Dimensions above ground 28in. inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

S	S	S	S
I	I2	7	8
NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter NO B.T.T.

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? YES

If not, why? _____

A. Friesen

(Signature)

10-10-35


(Date)

(Title)

E-1

Corner again.
metal poster on a tam. 3in. from which
this corner bears N 11 E 46 links

Give any further facts which will aid in finding this
chains distant.
from which this Corner bears S2W
side of tree
tree 12 inches diameter, on the NORTH
Metal Location Poster is on a cedar



(Make sketch of topography near Corner)

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

E-1

CORNERS OF THE PUBLIC SURVEY

T. 144 R. 26427 5th Mer.Sec. Corner common to Sections
1, 6, 7, and 12.Corner consists of a stake (not) in place
State conditionDimensions above ground 4" X 12" inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and
fill blanks below, giving bearings from Corner to Trees and
Distances in Links.

Species _____

Diameter No B. T.'s.

Bearing _____


Distance _____

Do you believe this to be a genuine Land Office Corner? ?

If not, why? No B. T.'s. and no scribing.
Evidently re-established by sec.
subdivision surveyor.Dana F. Kirkman
(Signature)Forest Ranger
(Title)3/12/28
(Date)

Handwritten notes on a grid background, including the word "Supr." and "In smart size town".

Corner again.
Give any further facts which will aid in finding this
chains distant.
from which this Corner bears
side of
tree inches diameter, on the
Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 144 R. 26 427 5th Mer

already posted

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

E-1

CORNERS OF THE PUBLIC SURVEY

T. 144 R. line 26-27 Mer.

Section Corner common to Sections
1, 6, 7, and 12

Corner consists of a Cedar Post (not) in place

State condition Good

Dimensions above ground 28 in inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

S	S	S	S
1	12	7	6

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter No B.T.

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

A. Friesen

(Signature)

10/10/35
(Date)

(Title)

U. S. DEPARTMENT OF AGRICULTURE

BUREAU OF LAND MANAGEMENT

UNITED STATES DEPARTMENT OF AGRICULTURE

CORNER OF THE PUBLIC SURVEY

from which this corner bears
N 11 E 46 1/2 Ks.

Corner again.

Give any further facts which will aid in finding this

329 chains distant


from which this Corner bears

S 2 W

side of tree

tree 12 inches diameter, on the North

Metal Location Poster is on a



(Make sketch of topography near Corner)