

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 144ⁿ R. 26^w 5th P Mer.
W.C. 1/16 Corner common to Sections
_____, _____, and 7

Corner consists of a _____ (not) in place
State condition _____

Dimensions above ground _____ inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	1/16 S		
	B.T.		

Species _____ T. JD _____

Diameter _____ 8" _____

Bearing _____ N 80 W _____

Distance _____ 12 LKS. _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

H. Hanson

(Signature)

8/8/35

(Date)

C.O.P.

(Title)

U. S. Department of Agriculture

FOREST SERVICE

123

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 N R. 26 W 5th Mer.

W.C. 1/16 Corner common to Section

7, and

Corner consists of a (not) in place



State condition

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION




N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species TAM Snag 4' high

Diameter 6"

Bearing N 80° W

Distance 10 LINKS

Do you believe this to be a genuine Land Office Corner? YES

If not, why?

2/8/35 Hanson (Signature) (Date)

Corner again.

Give any further facts which will aid in finding this


16.4 K.S. distant.

from which this Corner bears N. 60° E. side of

tree 60 inches diameter, on the

Metal Location Poster is on a T.M.

	Sec.		Sec.
	Sec.		Sec.



(Make sketch of topography near Corner)