

U. S. Department of Agriculture
FOREST SERVICE

X-5

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145 N. R. 26 W. Mer.

Sec. 31 and 32
Corner common to Sections

Corner consists of a _____ (not) in place
State condition New treated post

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

| | | | |
|---|---|---|---|
| | | | |
| N | W | S | E |

| | | | |
|----|----|----|----|
| | | | |
| NW | SW | SE | NE |

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

| | | | |
|--|--|--|--|
| | | | |
| | | | |

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? **No**

If not, why? F. S. established.

Ray W. Fassett
(Signature)


Sept 1953
(Date)

(Title)

X-5

Give any further facts which will aid in finding this
 Corner again. Set & treated post $3\frac{1}{2}$ feet
 high at point surveyed by 1951 crew. Post
 is scribed "SC" of F.S.L.P. tag put on
 5" red pine S 79° W 0.30 ch. This corner
 is S 89° 56' W. 5.00 ch. from the corner
 of Secs. 5 & 6 of T 174 N., R. 26 W. which
 is marked by a similar post.

Metal Location Poster is on a
 tree _____ inches diameter, on the
 side of _____
 from which this Corner bears
 _____ chains distant.



(Make sketch of topography near Corner)

T. 175 N. R. 26 W. M. 1
 X-5