

A-7

U. S. Department of Agriculture
FOREST SERVICE



Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 N. R. 26 W. 5th Mer.
N. 1/4 Corner common to Sections

Corner consists of a _____ (not) in place
State condition _____

Dimensions above ground _____ inches
Sketch grooves, letters, figures, or notches, on proper face or edge.



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____
Diameter _____
Bearing _____
Distance _____


Do you believe this to be a genuine Land Office Corner? **No**
If not, why? **F. S. established.**

Ray W. Jassett
(Signature)
Sept 1953
(Date) (Title)

A-7

Corner again. Set treated post at point surveyed by 1951 crew. Post is 3 1/2 feet high and is scribed "1/4 95". It is on dry land at east edge of swamp. Put F.S. L.P. tag on 7" spruce N. 67 E. 0.20 ch. A 6" balsam is N. 63 W. 0.30 ch. A 7" cedar is S. 21° E. 0.06 ch.

Give any further facts which will aid in finding this chains distant.
From which this Corner bears
side of
tree inches diameter, on the
Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 144 N. R. 26 W. Mer.

A-7

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

A-7

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 N. R. 26 W. 5th Mer.

N. 1/4 Corner common to Sections
....., and 5

Corner consists of a (not) in place
State condition

Dimensions above ground inches
Sketch grooves, letters, figures, or notches, on proper face or edge.
CARDINAL POSITION DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species
Diameter
Bearing
Distance

Do you believe this to be a genuine Land Office Corner? No
If not, why? F. S. established.


J. S. ...
(Signature)

50
(Date)

(Title)

Metal Location Poster is on a tree _____ inches diameter, on the _____ side of _____ from which this Corner bears _____ chains distant.

Give any further facts which will aid in finding this Corner again. Set treated post at point surveyed by 1951 crew. Post is $\frac{3}{4}$ feet high and is sorbed $\frac{1}{4}$ 85". It is on dry land at east edge of swamp. Put N.S. L.P. tag on 7" spruce N. 67 E. 0.20 ch. A 6" balsam is N. 63 W. 0.30 ch. A 7" cedar is S. 21° E. 0.06 ch.



(Make sketch of topography near Corner)

T. W. R. 26 N. Mer.