

U. S. Department of Agriculture

FOREST SERVICE

2-9

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145 N . R. 26 W. Mer.

Sec. Corner common to Sections

32, and 33

Corner consists of a (not) in place

State condition New treated post

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? No

If not, why? F. S. established

Ray W Jassett
Sept 1953
(Signature)

(Date)


(Title)

2-9

Corner again. Set treated post sorbed
 "SGO 32/33" at point designated by 1951
 W.O. survey crew. Post is at east edge
 of small open swamp. RSLP tag placed on
 7" spruce N. 64 E. 0.20 ch. A 6" balsam
 is N. 63 W. 0.30 ch. A 7" cedar is
 S 21° E. 0.06 ch. Corner is 5.15 ch.
 west of edge of Sec. 7 & 5 of T. 147 N.
 which is marked by similar post.

Metal Location Poster is on a
 tree _____ inches diameter, on the
 side of _____
 from which this Corner bears _____
 chains distant.

Give any further facts which will aid in finding this
 Corner again. Set treated post sorbed



(Make sketch of topography near Corner)

T. 145 N. R. 26 W. Mer. 2-9

U. S. Department of Agriculture
FOREST SERVICE

11-16-34
123
2-9

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 R. 26 5th Mer.

Sec. Corner common to Sections
32, and 33

Corner consists of a Wooden Post (not) in place
State condition Good

Dimensions above ground 3.6 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

T 144			T 144
S 32			S 33

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

H. A. Brills

(Signature)

Chief of Party

7/26/34
(Date)

2-9

Faint, illegible text on a ruled background, possibly bleed-through from the reverse side of the page.

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T 144 R 26 S 4 Mer.