

U. S. Department of Agriculture
FOREST SERVICE

2-11

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145 N. R. 26 W. Mer.

S. 4 Corner common to Sections
32 and 33

Corner consists of a _____ (not) in place
State condition New treated post

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION




N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? **Yes**

If not, why? _____

Ray W. Fassett
(Signature)
Sept 1953
(Date)


(Date)

(Title)

2-11

Give any further facts which will aid in finding this Corner again. Found old P.S. poster and rotted tamarack stub with traces of scribbling. Conceded this to be original 37 Cor. of 33 and set treated post scribbled "37C-333". Point designated by 1951 M.O. survey drew for this corner is 2x2 treated stake 3 67 E 0.96 ch.

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant.



(Make sketch of topography near Corner)

T. 17S N.

R. 26 W.

Mer.

Z-11