

U. S. Department of Agriculture

FOREST SERVICE

N-12

123

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 R. 26 Mer.

1/16 Corner common to Sections
16, and 21

Corner consists of a square stake (not) in place

State condition badly decayed

Dimensions above ground 18 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

1/16 S		1/16 S	
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/16 S		1/16 S	
B.T.		B.T.	

Species Elm Elm

Diameter 7 in. 10 in.

Bearing N 60° W S 52° W

Distance 0.1656 0.144

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

A. Friesen

(Signature)

10/28/35

(Date)

2-7394


N-12

(Title)

Corner again.
Give any further facts which will aid in finding this

chains distant.
0.14
from which this Corner bears
S 52° W
side of TRS
tree 10 inches diameter, on the North east
Metal Location Posters on a Elm - B.I.

I put up



(Make sketch of topography near Corner)

Form 874-0—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

N-12

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 W. R. 26 W. Mer.

E 1/16

Corner common to Sections

16, and 21

Corner consists of a _____ (not) in place

State condition New treated post

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? **No**

If not, why? _____

Ray W. Jassett

(Signature)

(Date)


Sept 19 1953

(Title)

N-12

Set treated post 3"x3 1/2" feet high scribed
#1/16 SC".
Corner again.
Give any further facts which will aid in finding this
chains distant.

from which this Corner bears
side of
tree inches diameter, on the
Metal Location Poster is on a



(Make sketch of topography near Corner)

U. S. Department of Agriculture

FOREST SERVICE

N-12

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 N. R. 26 W. Mer.

E 1/16

Corner common to Sections

16, and 21

Corner consists of a (not) in place

State condition New treated post

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? No

If not, why?

F. M. M.


(Signature)

53

(Date)

(Title)

Get treated post 3"x3 1/2" feet high scribed
 "1/16 80"
 Corner again.
 Give any further facts which will aid in finding this
 chains distant.
 from which this Corner bears
 side of
 tree inches diameter, on the
 Metal Location Poster is on a



(Make sketch of topography near Corner)