

U. S. Department of Agriculture

FOREST SERVICE

123

P-13

Chippewa NATIONAL FOREST

P

CORNERS OF THE PUBLIC SURVEY

T. 144 N R. 26 W 5th Mer.

1/4 Corner common to Sections

21, and 22

Corner consists of a No Stake (not) in place

State condition

Dimensions above ground inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	1/4 S	F. S. L. P.	
(BT.)	(BT.)		

Species Cedar Cedar cedar

Diameter 8" 12" 10"

Bearing N67W N52E S80E

Distance .09 .09 .23

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

Earl M. Handy

(Signature)

Chief of Party

(Date)

P-13


(Title)

X

Corner again.
 The 2 BIT'S are LYING ON
 ground & badly rotted - both
 have been sawed off. One
 has been sawed off below scribbling
 and the other above scribbling.

Give any further facts which will aid in finding this
 chains distant.

23
 from which this Corner bears N 80 W
 side of said tree
 tree 10" inches diameter, on the NW
 Metal Location Poster is on a Cedar



(Make sketch of topography near Corner)

T. 144 N. R. 26 W. S. 14 Mer.

U. S. Department of Agriculture

FOREST SERVICE

P-13

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 R. 26 5¹/₄ Mer.1/₄ Corner common to Sections
21, and 22Corner consists of a No Stake (not) in place
State condition _____Dimensions above ground _____ inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E


--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and
fill blanks below, giving bearings from Corner to Trees and
Distances in Links.

			
(B.T.)	(B.T.)		

Species Cedar Cedar CedarDiameter 8" 12" 10"Bearing N. 67 W N. 52 E S. 80 EDistance 9 1/2 9 1/2 23 1/2Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Carl M. Handy

(Signature)

Chief of Party


(Title)

(Date)

R

The 2 B.T.s. are lying on ground & badly rotted - both have been sawed off. One has been sawed off below scribbling and the other above scribbling.

Corner again. Give any further facts which will aid in finding this 23 lks. chains distant. from which this Corner bears N. 80 W. side of said tree 10" inches diameter, on the N. W. Metal Location Poster is on a Cedar



(Make sketch of topography near Corner)

Form 874-9—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

P-13

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 1 1/4 N. R. 26 W. Mer.

Corner common to Sections 21 and 22

Corner consists of a post (not) in place


State condition new treated post

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? **No**

If not, why? _____

Ray W. Jassett

(Signature)

Sept 1913
 (Date)

(Title)

P-13

Chipmunks

0.69 ch.

S. 70° W. 0.22 ch. and 6" birch N. 120° W.
10" cedar bears S. 80 E. 0.28" a 5" birch

edge. Post scribbled "1/4 80" from which

In a swamp about 3 ch. south of the north
high at spot located by 1951 survey crew.

Corner again. Set 7" treated post 3/4 feet

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 177 N. R. 26 W. Mer. P 13

U. S. Department of Agriculture
FOREST SERVICE

P-13

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 N. R. 26 W. . . . 5th Mer.

1/4 Corner common to Sections
21, and 22

Corner consists of a _____ (not) in place
State condition New treated post.

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner?

If not, why? _____

Fennell

(Signature)

5-3


(Date)

(Title)

W 1/2 N

10' cedar bears S. 80 E. 0.28' a 5' birch
 S. 70 W. 0.22' ch. and 6" birch N. 12° W.
 0.26' ch.

edge. Post scribed "1/4 80" from which
 In a swamp about 3 ch. south of the north
 high at spot located by 1951 survey crew.
 Corner again. Set 7" treated post 3 1/2 feet
 Give any further facts which will aid in finding this
 from which this Corner bears
 side of
 tree inches diameter, on the
 Metal Location Poster is on a



(Make sketch of topography near Corner)