

U. S. Department of Agriculture  
FOREST SERVICE

123

L-13

Chippewa NATIONAL FOREST P

CORNERS OF THE PUBLIC SURVEY

T. 144 N R. 26 W 5 th. Mer.

1/4 Corner common to Sections

15, and 16

Corner consists of a no stake (not) in place

State condition

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/4 S			
-------	--	--	--

BT			
----	--	--	--

Species Larch

Diameter 8"

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

Earl M. Handy


(Signature)

Chief of Party

(Date)

L-13

(Make sketch of topography near Corner)



Metal Location Poster is on a tree.....inches diameter, on the side of ..... from which this Corner bears ..... chains distant. Give any further facts which will aid in finding this Corner again.

U. S. Department of Agriculture  
FOREST SERVICE

L-13

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 N. R. 26 W. 5th Mer.

1/4 Corner common to Sections

15 and 16

Corner consists of a \_\_\_\_\_ (not) in place


State condition New treated post

Dimensions above ground \_\_\_\_\_ inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

Ray W. Jamieson  
(Signature)

Sept 1953  
(Date)


(Title)

L-13

Original G.L.O. spruce B.T.S 59° E.  
 0.18 ch. was recovered. A 7" cedar bears  
 S. 53° E. 0.35 ch. and an 8" spruce  
 N. 52° W. 0.13 ch.

Set 5" treated post 4 feet high in swamp.  
 Corner again. Now marked post  
 Give any further facts which will aid in finding this  
 chains distant.

from which this Corner bears  
 side of  
 tree inches diameter, on the  
 Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 127 N. R. 26 W. Mer. T-13

U. S. Department of Agriculture

FOREST SERVICE

L-13

Chippewa

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 14 N. R. 26 W. 5th Mer.

1/4

Corner common to Sections

15, and 16

Corner consists of a \_\_\_\_\_ (not) in place

State condition New treated post

Dimensions above ground \_\_\_\_\_ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

*Farratt*

(Signature)


53

(Date)

(Title)

Set 9<sup>th</sup> located post 4 feet high in swamp.  
Original O.L.O. across B.T. S 59° E.  
0.18 ch. was recovered. A 7<sup>th</sup> cedar bears  
S. 41° E. 0.38 ch. and an 8<sup>th</sup> hemlock  
N. 52° W. 0.13 ch.  
Corner again.

Give any further facts which will aid in finding this  
from which this Corner bears  
side of  
tree inches diameter, on the  
Metal Location Poster is on a



(Make sketch of topography near Corner)