

Form 874-G—Revised May, 1918  
 U. S. Department of Agriculture  
 FOREST SERVICE

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 N R. 26 W 5<sup>th</sup> Mer.

1/4 Corner common to Sections  
 \_\_\_\_\_, \_\_\_\_\_, and 10

Corner consists of a Wood stake (not) in place  
 State condition Badly Rotted

Dimensions above ground 2' X 3" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

1/4 S	1/4 S	1/4 S	1/4 S
NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/4 S			
B.T.			

Species Aspen

Diameter 8"

Bearing 56° W

Distance 10

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

E. M. Handy


(Signature)

(Date)

S. O. P.  
 (Title)

Give any further facts which will aid in finding this  
Corner again.

Metal Location Poster is on a  
tree 8 inches diameter, on the  
side of *Said tree*  
from which this Corner bears  
N 6° E  
chains distant



(Make sketch of topography near Corner)

Form 874-9—Revised May, 1918  
 U. S. Department of Agriculture  
 FOREST SERVICE

11-19-34  
 123

Chippewa NATIONAL FOREST  
 CORNERS OF THE PUBLIC SURVEY

T. 144 N R. 26 W 5th Mer.

1/4 -

Corner common to Sections

and 10

Corner consists of a Wood stake (not) in place

State condition Badly Rotted.

Dimensions above ground 2' x 3" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

1/4	1/4	1/4	1/4
-----	-----	-----	-----

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/4			
B.T.			

Species Aspen

Diameter 8"

Bearing S6°W

Distance 10

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

E. M. Handy

(Signature)

Co. P.

(Title)

(Date)

G-15

Corner again.

Give any further facts which will aid in finding this

chains distant.

10

from which this Corner bears

N 60 E

side of


Spruce tree

tree inches diameter, on the

NW

Metal Location Poster is on a

Ash



(Make sketch of topography near Corner)

T. 144N R. 26W 5th Mer.