

Form 874-B—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

E-15-23-24
133

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 R. 26 5 Mer.

44 Corner common to Sections

3, and 10

Corner consists of a Squared STUMP (not) in place

State condition Slightly Rotten

Dimensions above ground 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species N. PINE

Diameter 12"

Bearing S 74° E

Distance 24 Links

Do you believe this to be a genuine Land Office Corner? NO

If not, why? Not in Place & does Not

Check to other Corners

Established by Ranger Soderback.

H. A. Brill

(Signature)

C. C. C. Surveyor

(Title)

3/16/34
(Date)

E-15

Forest Service Marker
ON Road 5.24 chains East
Corner is a squared
Ash stump 3 ft above
ground

Corner again.

Give any further facts which will aid in finding this


24 links equals distant.

from which this Corner bears N. 74° W

side of Tree

tree 12 inches diameter, on the West

Metal Location Poster is on a Norway Pine



(Make sketch of topography near Corner)

T. 144 R. 26 Mer. 5

E-15

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144. N. R. 26 W. 5th Mer.

1/4. Corner common to Sections 30, 31, and 10

Corner consists of a (not) in place



State condition **new treated post**

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? **No**

If not, why? 3

F.S. established.

Ray W Jassett
(Signature)

(Date)

(Title)

E-15

DEPT. OF THE INTERIOR

Set 7" treated post $3\frac{1}{2}$ feet high and scribed "750 3/10" from which F.S.L.P. on 16" Burr Oak bears north about 0.30 chains. This is a F.S. established corner as there was no conclusive evidence of original G.L.O. survey.

Corner again. New treated post. Give any further facts which will aid in finding this


chains distant. 0.30

from which this Corner bears south

side of said tree

tree 16 inches diameter, on the south

Metal Location Poster is on a Burr Oak



(Make sketch of topography near Corner)

U. S. Department of Agriculture
FOREST SERVICE

E-15

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 N. R. 26 W. 5th Mer.

1/4 Corner common to Sections
3, and 10

Corner consists of a (not) in place
State condition new treated post

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? No

If not, why?

F.S. established.

Jas. J. [Signature]

(Signature)

53

(Date)

(Title)

