

U. S. Department of Agriculture

FOREST SERVICE

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 R. 26 5<sup>th</sup> Mer.

14 Corner common to Sections  
34 & 35, and

Corner consists of a iron pipe (rust) in place  
State condition good.

Dimensions above ground 18 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

Norman P. Shaw

(Signature)

Mar. 6, 35 Engineer

(Date)

(Title)

Corner again.

Give any further facts which will aid in finding this

20 chains distant.


from which this Corner bears

West

side of post.

tree 6 inches diameter, on the West

Metal Location Poster is on a fence post.



(Make sketch of topography near Corner)

T. 147 R. 26 5th Mer.