

U. S. Department of Agriculture

FOREST SERVICE

Z-19

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 N. R. 26 W. Mer.

S 1/4 Corner common to Sections

....., and 35

Corner consists of a ..... (not) In place

State condition .....

Dimensions above ground ..... inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of ..... is located .....

Pits are located .....

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species .....

Diameter .....

Bearing .....

Distance .....

Do you believe this to be a genuine Land Office Corner? **No**

If not, why? .....

*Ray W. Jassett*  
(Signature)  
*Sept 1953*  
(Date)

(Title)


Z-19

Section 35

Corner of the public highway

This is a U.S. established corner. It is in a cedar swamp and marked by a 7' post 31 feet high. Post marked by a 7' 1 1/4 x 1 1/2" W. 50 W. 1788

Give any further facts which will aid in finding this corner again.  
from which this corner bears S 110 E. side of said tree 4 inches diameter, on the Metal Location Poster is on a



(Make sketch of topography near corner)

T. M. R. 26 W.

Mer. Z-19

U. S. Department of Agriculture

FOREST SERVICE

2-19

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 24 N. R. 26 W. Mer.

Corner common to Sections

12, 13, 14, 15, 16, 17, 18, 19, 20, 21, 22, 23, 24

Corner consists of a (not) in place



State condition

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION




N W S E NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner?

If not, why?

Handwritten signature

(Signature)

4-5-3

(Date)

(Title)

(Title)

NATIONAL FOREST

CORNER OF THE PUBLIC SURVEY

This is a P.S. established corner. It is in a cedar swamp and marked by a 7" post 31 feet high. Post set by 11/4 & 35'.  
Corner again.

Give any further facts which will aid in finding this


chain distant: 0.18

from which this Corner bears S 11° E.

side of said tree

tree 4 inches diameter, on the SE

Metal Location Poster is on a cedar



(Make sketch of topography near Corner)