

U. S. Department of Agriculture
FOREST SERVICE

V-21

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 N., R. 26 W., S. 30. Mer.

Corner common to Sections 18

25, 26, 35, and 36 of a 100 A. 100 F.

Corner consists of a _____ (dot) in place

State condition New treated post

Dimensions above ground 42 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	32		38

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Ray W. Jarrett
(Signature)

Sept 1953
(Date)

(Title)

V-21

children

line to the south.

0.56 on N of road and opposite fence

36 feet high and called "No. 1" Post is

S.E. which is in road. Post 7" post

This is a witness corner to the true

Corner again. New treated post

Give any further facts which will aid in finding this


chains distant

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

V-21

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 N. R. 26 W. Mer.

Sec. _____ Corner common to Sections
25, 26, 35, and 36

Corner consists of a _____ (not) in place
State condition New treated post

Dimensions above ground 42 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ Is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner?

If not, why? _____

R. W. Fassett

(Signature)

Sept 1953

(Date)

(Title)

This is a witness corner to the true
S.O. which is in road. Set 7" post
36 feet high and set back 40". Post is
0.55 ch. N of road and opposite fence
line to the south.

Corner again.

Give any further facts which will aid in finding this


chain distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)