

Form 874-B—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144N R. 27E28W 5th - Mer.

Meander Corner common to Sections
19, and 24

Corner consists of a Iron pipe (set) in place
State condition Good

Dimensions above ground 2" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>144</u> <u>27</u> <u>MC</u> <u>319</u>
--

<u>144</u> <u>28</u> <u>MC</u> <u>324</u>
--

--

--

<u>BT.</u>

<u>BT.</u>

--

--

Species Tam Tam

Diameter 7" 4"

Bearing East N15W

Distance 40 35

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

E. M. Hardy
(Signature)

(Date)

(Title)

WATER RESOURCES DIVISION

FIELD NOTES

DATE: 1948


Give any further facts which will aid in finding this corner again.

From which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)