

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

A 5

CORNERS OF THE PUBLIC SURVEY

T. T144N R. R27W 5th Mer.

Section Corner common to Sections
6, and 5

Corner consists of a brass capped pipe (not) in place

State condition good

Dimensions above ground 5 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N * * *

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T¹ 5
R27
6

T² 5
R27
5

B.T.

B.T.

Species NPins

Diameter 1 1/2"

Bearing S 86° W

Distance 38 1/2

Do you believe this to be a genuine Land Office Corner?

If not, why? _____

(Signature)

1/11/41
(Date)

(Title)

Faint, illegible text on the top half of the page, possibly bleed-through from the reverse side.

Corner again. Give any further facts which will aid in finding this


chain distant.

From which this Corner bears *34* *5.16° E*

side of *Tree*

tree *5* inches diameter, on the *North*

Metal Location Poster is on a *field*



(Make sketch of topography near Corner)

T. 14 N. R. 27 W. 5th Mer.