

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

2-8

CORNERS OF THE PUBLIC SURVEY

T. 104N R. 27W 5th Mer.

16 Corner common to Sections

28, 29, and 30

Corner consists of a \_\_\_\_\_ (not) in place


State condition \_\_\_\_\_

Dimensions above ground \_\_\_\_\_ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? No

If not, why? No evidence

[Signature]

(Signature)

Asst. Dir.

(Title)

1/16/61  
(Date)

~~Block + Block like formation~~  
~~East side corner~~

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of ~~the~~

tree 13 inches diameter, on the ~~East~~

Metal Location Poster is on a ~~Map of~~



(Make sketch of topography near Corner)

T. VAN R. 2-7 Mer. 5-24