

U. S. Department of Agriculture
FOREST SERVICE

N-11

CHIPPWA NATIONAL FOREST P.

CORNERS OF THE PUBLIC SURVEY

T. 14th N. R. 27 W. S. 6th Mer.

1/4 cor. Corner common to Sections
10, and 21

Corner consists of a two sided stake (not) in place
State condition fair

Dimensions above ground 0' high inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

SLP			

Species cedar

Diameter 0"

Bearing S80W

Distance 00 lks.

Do you believe this to be a genuine Land Office Corner? NO

If not, why? there are no bearing trees and no scribbling on stakes.

E. Gordon
Chief of Party

E.H.

(Date)

(Title)

Corner again.

Give any further facts which will aid in finding this

chains distant.


• 50

from which this Corner bears North 80 West

side of said tree

tree 5" inches diameter, on the North West

Metal Location Poster is on a



(Make sketch of topography near Corner)