

U. S. Department of Agriculture

FOREST SERVICE

Q-14

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144N R. 27W 5th Mer.

1/16 Corner common to Sections \_\_\_\_\_, \_\_\_\_\_, and 22



Corner consists of a \_\_\_\_\_ (not) in place State condition \_\_\_\_\_

Dimensions above ground \_\_\_\_\_ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION




N W S E

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? No evidence

*[Handwritten Signature]*

(Signature)


Asst DFR

(Title)

1/12/61  
(Date)

Corner again.  
Blue line & blazed line  
North & East of corner

Give any further facts which will aid in finding this  
chains distant.  
From which this Corner bears  
side of  
tree inches diameter, on the  
Metal Location Poster is on a



(Make sketch of topography near Corner)

T. W. R. 27W  
Mer.