

U. S. Department of Agriculture
FOREST SERVICE

P-14

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. ~~144N~~ R. 27W 5 Mer.

1/16 Corner common to Sections
_____, _____, _____, and 22



Corner consists of a _____ (not) in place
State condition _____

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner?

If not, why? No evidence

R. J. E. Jones

(Signature)

1/12/61


(Date)

Asst. D.F.R.

(Title)

(Make sketch of topography near Corner)

T. 14N R. 27W S Mer.



Metal Location Poster is on a **PK Spruce**

tree 7 inches diameter, on the **SW**

side of **Tree**

from which this Corner bears

chains distant.

Give any further facts which will aid in finding this

Corner again.

Blue line painted South

West of corner

Blazed line South of corner