

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

R-17

NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 144 R. 27 Mer.

Corner common to Sections
22, 23, 26, and 27

Corner consists of a Pipe + brass cap (not) in place
State condition Good monument

Dimensions above ground 8" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species None located

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? _____

If not, why? Yes - brass cap


R. H. Christensen
(Signature)

Oct-58
(Date)

R. E. R.
(Title)

Corner again.
Central on Alex. 18th Post approx
8 ch south on Ferryway 22
Corner on edge of lobby looks
little like west over corner.

Give any further facts which will aid in finding this
chains distant.
from which this Corner bears
side of corner about 1 chain.
tree 1/4 inches diameter, on the West & South
Metal Location Poster is on a Topo on 2 base.



(Make sketch of topography near Corner)