

U. S. Department of Agriculture  
FOREST SERVICE

Chippewa NATIONAL FOREST

L-17

CORNERS OF THE PUBLIC SURVEY

T. 144N. R. 27W. 5th P. Mer.

1/4 Corner common to Sections  
14, and 15

Corner consists of a Iron Pipe (not) in place


State condition Good

Dimensions above ground 2" X 12" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>1/4</u> <u>S 14</u>	<u>1/4</u> <u>S 15</u>		
<u>B.T.</u>	<u>B.T.</u>		

Species Tam. Tam.

Diameter 5" 5"

Bearing N 90° E S 34° W

Distance 25 Lks. 75 Lks.

Do you believe this to be a genuine Land Office Corner? Yes.

If not, why? \_\_\_\_\_

E. M. Handy  
(Signature)

1/28/38  
(Date)


(Title)

-----  
 -----  
 -----  
 -----  
 -----

Location Poster on Section  
 22 & 23 on the Mud Lake Road  
 This cor. is due N. from this  
 C.P.

Corner again.  
 Give any further facts which will aid in finding this  
 chains distant.  
 from which this Corner bears

side of  
 tree inches diameter, on the bearing tree  
 Metal Location Poster is on a  
 (One on each)



(Make sketch of topography near Corner)

T. 144 N. R. 27 W. S4 P. Mer.

Form 874-0—Revised May, 1913  
U. S. Department of Agriculture  
FOREST SERVICE

Chippewa NATIONAL FOREST

2-17

CORNERS OF THE PUBLIC SURVEY

T. T 144 N R. 27 W 5<sup>th</sup> P. Mer.

1/4 Corner common to Sections

14, and 15

Corner consists of a iron pipe in place

State condition Good

Dimensions above ground 2" x 12" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION


N W S E


NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/4  
S. 14

1/4  
S 15

B.T.

B.T.

Species Tam Tam

Diameter 5" 5"

Bearing N. 40 E S 34 W

Distance 25 lks 75 lks

Do you believe this to be a genuine Land Office Corner? Yes.

If not, why? \_\_\_\_\_

12

(Signature)


7/7/41

(Date)

(Title)

Corner again.  
Location Poster on my table.  
North of this corner is due

Metal Location Poster is on a *one on each B.I.*  
tree inches diameter, on the  
side of  
from which this Corner bears  
chains distant.  
Give any further facts which will aid in finding this



(Make sketch of topography near Corner)

T. 14 N. R. 27 W. 5th P. Mer.