

Form 874-B—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

221

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 144N. R. 27W. 5th P. Mer.

1/4 Corner common to Sections
25, and 26

Corner consists of a Iron pipe in place

State condition Good

Dimensions above ground 2" x 12" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/4
S 25

1/4
S 26

B.T.

B.T.

Species Aspen Cedar

Diameter 5" 8"

Bearing S 57° E N 39° 30' W

Distance 30 lks 81 lks

Do you believe this to be a genuine Land Office Corner? Yes.

If not, why? _____

E. M. Hardy
(Signature)

1/19/38
(Date)

(Title)

U. S. Department of Agriculture

Location Poster on Chas. Lyons
road about 1/4 mile S. of this cor.

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 194N. R. 27W. 5th P. Mer.

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 R. 27 5th Mer.

1/4 Corner common to Sections
25, and 26

Corner consists of a Wood Stake (not) in place
State condition Fair

Dimensions above ground 2" x 5" x 3 1/2" inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

F.S.L.P.	1/4 S		
	Crayon		
	526		

Species Spruce Spruce

Diameter 8" 11"

Bearing N. 65 W. Due W.

Distance 10 lks 3 ft.

Do you believe this to be a genuine Land Office Corner? No

If not, why? No bearing trees and no scribing on Stake.

The Scribe was in Crayon.

C. Gordon

(Signature)


Chief of Party

(Date)

(Title)

Corner again.
 No. of 1/4 line between 25 +
 26 has been cut for cedar.
 Monkey face on same tree
 (11" spruce) as is the metal
 poster.

Metal Location Poster is on a spruce
 tree 8" inches diameter, on the south west
 side of said trees
 from which this Corner bears S. 65 E.
 10 1/2 chains distant.
 Give any further facts which will aid in finding this



(Make sketch of topography near Corner)

T. 144 R. 22 Mer. 5th