

U. S. Department of Agriculture
FOREST SERVICE

5-22

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 R. 27 52 Mer.

1/16 Corner common to Sections
25, _____, and _____

Corner consists of a metal tag (not) in place

State condition good

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner?

If not, why? No evidence

S. M. Marwan

(Signature)

Forester and


(Title)

3/30/59
(Date)

UNITED STATES GEOLOGICAL SURVEY

Corner again.
Blair Line fence
North from corner

Metal Location Poster is on a *Yucca*
tree 6 inches diameter, on the *North*
side of *the*
from which this Corner bears
chains distant.
Give any further facts which will aid in finding this



(Make sketch of topography near Corner)