

U. S. Department of Agriculture
FOREST SERVICE

23

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 R. 27 5th Mer.

1/4 Corner common to Sections

24, 25, and

Corner consists of a *Iron Pipe & Rock* (not) in place
Esquered post State condition *good poor*

Dimensions above ground 3 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? *Re-survey of 1937*


Stanley M. Morrison

7/8/58
(Date)

Forestry Aid
(Title)

Corner again.
130 yds line running East
& West line about 100 yds
each end of corner

Give any further facts which will aid in finding this
corner distant.
3 feet
from which this Corner bears North
side of tree
tree 6 inches diameter, on the North
Metal Location Poster is on a Bloom



(Make sketch of topography near Corner)