

U. S. Department of Agriculture  
FOREST SERVICE

R-24

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 R. 27 52 Mer.

132 Corner common to Sections  
25, \_\_\_\_\_, and \_\_\_\_\_

Corner consists of a metal tag (set) in place  
State condition good

Dimensions above ground \_\_\_\_\_ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner?

If not, why? No evidence

J. M. Morrison

(Signature)

Forestry Aid

(Title)

3-30-59

(Date)

-----  
-----  
-----  
-----  
-----

*from corner*

*Blue Line Poster*  
Corner again.


Give any further facts which will aid in finding this chains distant.

from which this Corner bears

side of *tree*

tree 7 inches diameter, on the *west*

Metal Location Poster is on a *corner*



(Make sketch of topography near Corner)

T. 144 R. 27 S. 2 Mer.