

U. S. Department of Agriculture

FOREST SERVICE

E-1

CHIPPEWA NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. ~~164~~ R. 28 & 29 S. 5 Mer.

Section Corner common to Sections

1, 6, 7, and 12

Corner consists of 10 iron pipe (10) in place


State condition excellent

Dimensions above ground 12 inches.


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

FSLP. T144 R 28&29			
--------------------------	--	--	--

B.T.			
------	--	--	--

Species N.P. _____

Diameter 28" _____

Bearing N-NW _____

Distance 300 ft North and 2 chs West _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

(Signature)

(Date)


(Title) E-1

Map

to box car and trail so indicated on M
See line R.B. X then take tracks RSE
by walking down Portage Lake Road to
corner is in a swamp it can be found
Corner again.

Give any further facts which will aid in finding this
300' south ~~east~~ distant.

from which this Corner bears 2 chains East and
side of said Norway pine
tree 28 inches diameter, on the East
Metal Location Poster is on a Norway Pine



(Make sketch of topography near Corner)

U. S. Department of Agriculture
FOREST SERVICE

D. R. E-1

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 R. 28 & 29 5th Mer.

Sec. _____ Corner common to Sections
1, 6, 7, and 12

Corner consists of a G. & O. iron pipe (not) in place

State condition Excellent

Dimensions above ground 12 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

51	512	57	56
----	-----	----	----

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

F. S. L. P.
T. 144
R. 28 & 29

T. 144 N
R. 27
S. P.

T. 144 N
R. 29 W
S 6

B. T.

B. T.

B. T.

Species N. Pine N. Pine J. Pine

Diameter 28" 22" 11"

Bearing N-NW N. 5 W. N. 12 E.

Distance 300 ft N. + 2 chs. West. 4.10 lks. 4.20 lks.

Do you believe this to be a genuine Land Office Corner? Yes.

If not, why? _____

C. B. Stott
(Signature)


J. F.
(Title)

3/5/28
(Date)

Corner is in a swamp it can
 be found by walking down Portage Lake
 Road to Spaulding R.R. - then take tracks
 E.S.E. to box car and trail South,
 indicated on map.

4 chs. North to Pine ridge
 Corner again.

Give any further facts which will aid in finding this
 chains distant.
 from which this Corner bears
 side of
 tree inches diameter, on the described
 Metal Location Poster is on the B.T. which is



(Make sketch of topography near Corner)

T. 144 R. 28 & 29 5th Mer.