

U. S. Department of Agriculture  
FOREST SERVICE

D-6

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 R. 28 Mer.

1/16 SW 1/4-5 Corner common to Sections  
5, and \_\_\_\_\_

Corner consists of a \_\_\_\_\_ (not) in place  
State condition \_\_\_\_\_

Dimensions above ground \_\_\_\_\_ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

W. E. Heron  
(Signature)

1/28/58  
(Date)

(Title)

D-6

Corner again.

75" TYPE

Give any further facts which will aid in finding this


chains distant.

from which the Corner bears

side of

tree 8 inches diameter, on the

Metal Location Poster is on a Spruce SW



(Make sketch of topography near Corner)

T. R. Mer.