

U. S. Department of Agriculture

FOREST SERVICE

J-9

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 R. 28 5th Mer.

Sec. Corner common to Sections

8, 9, 16, and 17

Corner consists of a squared stake (not) in place

State condition Poor

Dimensions above ground 7 1/2 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Can't Read

Species Spruce

Diameter 3"

Bearing N. 15 W

Distance 30'

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

C. B. Stott (Signature)

6/22/26 (Date)

J. F. (Title)

J-9


U.S. GEOLOGICAL SURVEY

NATIONAL FOREST

CONTINENTAL DIVISION

Corner again.
 This corner is 2 chs. W of a
 squared sapling, a cut line runs
 thru both. The corner describ.
 However, has one B.T.

Give any further facts which will aid in finding this
 chain distant
 from which this Corner bears
 side of
 tree inches diameter, on the
 Metal Location Poster is on a



(Make sketch of topography near Corner)