

U. S. Department of Agriculture
FOREST SERVICE

B-13

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *144* R. *28* *5th* Mer.

1/2 N *116* Corner common to Sections
3, and *4*

Corner consists of a *yellow log* (~~not~~) in place

State condition *good*

Dimensions above ground *54"* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? *No*

If not, why? *No evidence of cornering*

Marion H. Gaudin

(Signature)

2/6/29
(Date)

Asst Dist For Range
(Title)

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree ⁵ inches diameter, on the ^{North}

Metal Location Poster is on a ^{Post}



(Make sketch of topography near Corner)

Mer.

R.

T.