

U. S. DEPARTMENT OF AGRICULTURE
FOREST SERVICE

Posted

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144N R. 29W 30W 5th Mer.

Sec. Cor. Corner common to Sections

1, 6, 7, and 12

Corner consists of a Pipe and cap (not) in place

State condition Good


Dimensions above ground 5" inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION



DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T. 144N
R. 29W
56

T. 144N
R. 30W
512

[Empty box]

[Empty box]

BT

BT

[Empty box]

[Empty box]

Species ELM ELM

Diameter 20" 15"

Bearing N65E S64W

Distance 150' 90'

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

O. P. Boerger

Signature.

12/27/30
Date.

Estimator


Title. E-1 3027

(Make sketch of topography near Corner.)

Mer.

R. 2944 + 3041 3/4

T. 124N



Metal Location Poster is on a

tree inches diameter, on the

side of

from which this Corner bears

chains distant.

Give any further facts which will aid in finding this

Corner again.

The post hole, bearing and distance

read stand coming up to level.

As per a brief description